





INSTALLATION INSTRUCTIONS

S6303M WIRING INSTRUCTIONS

SOLENOID WIRING INSTRUCTIONS



12VDC @ .6 AMP



24VDC @ .3 AMP

MONITORING OPTIONS WIRING INSTRUCTIONS

REX

WHT = COM
 YEL = N/O
 ORG = N/C

DPS

GRN = COM
 RED = N/O
 WHT = N/C

LS

WHT/BLK = COM
 ORG/BLK = SECURE
 YEL/BLK = UNSECURE